Quality Control

Work Order ID 69055 Wednesday, April 27, 2011 11:28:59 AM										-	Page 1
Revision ID: Item Name: Start Date: Required Date:	D3443-3 Clevis 4/27/2011 5/3/2011	Start Qty: 6.00 Req'd Qty: 6.00		Accept	Cust Item Customer:			WW s	Setup Star Stop		
Approvals:	Process Pla	nn:	Date J-DU-27	Tooling: SPC (Y/N):	-	ate:		F	Run Star Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr									
D3443	Rev	·C									
Doosan		Memo	I AC DED FOLIO FASRS & DU	0.00	€ 11 · Z ·	17		6			-
Doosan Lathe		FOLIO I DWG R	I AS PER FOLIO FA588 & DW REV: EV: JRR AS REQUIRED	VG 123443							
150		QC2- Inspect parts o	ff machine FAI/FAIB	0.00	يخ در٠ ٠٤٠	17		6			
QC Quality Control		Мето		0.00							
160		QC8- Inspect parts -	second check	0.00	W (1)	8		4			
QC		Memo		0.00	•						-

W/O:	-		W	ORK ORDER CHANG	ES							
DATE	STEP	PROC	EDURE CHA		Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
							·					
Part No	:	PAR #:	_ Fault Cate	gory:	NCR: Yes No DQA: Date:							
	Resolution:		_ Dispositio	n:	_ QA: N/C Clo	sed:	Date: _					
NCR:		W	ORK ORD	ER NON-CONFORMA	ANCE (NCR)		*					
DATE	OTED	Description of NC		Corrective Action Section		Verificatio	n Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector				
						i						
		,										
							,					
					# # # # # # # # # # # # # # # # # # #							
						-						
•												

Work Order ID 69055

Wednesday, April 27, 2011 11:28:59 AM



Page 2

Item ID:

D3443-3

Accept



Setup Start



Revision ID:

Start Date:

Item Name:

Clevis

4/27/2011

Start Qty: 6.00 Req'd Qty: 6.00

Cust Item ID:

Customer:

Tool ID

Reference:

A	DD	ro	va	IS	:

Process Plan:

Date: _____

Tooling:

Date:

Tool # Plan

Code

Run

Start

Stop

Stop

Required Date: 5/3/2011

QC:

Date:

SPC (Y/N):

Date:

Accept

Qty

Reject

Qty

Insp.

Stamp

Sequence ID/ **Work Center ID**

170

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

Memo

*****STOCK IN LARGE FAB*****

Set Up/ **Run Hours**

0.00

Reject

Number

180

QC21- Final Inspection - Work Order Release

0.00



Quality Control

Memo

0.00

W/O:			W	ORK ORDER CHANG	GES				î
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								,	
Part No	_	PAR #:	Fault Cat	togory:	NCD: Vas	No DC	١٨٠	Date	
raitino		esolution:							
NCR:		·	VORK ORI	DER NON-CONFORM	IANCE (NC	R)			
DATE	STEP	Description of NC	Iiai ai	ction B	Sign & Verifi		Approval	Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Date Section		Chief Eng	QC Inspector
						, i			

Picklist Print

Wednesday, April 27, 2011 11:29:05 AM

Work Order ID: 69055

D3443-3 Parent Item:

Parent Item Name: Clevis

Start Date: 4/27/2011

Required Date: 5/3/2011

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP Rev: A□05.11.14□New issue□EC□

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304R1.500		Purchased	No			100	f	15.3300	0.25	1.5			
										Re	il.	5.	17

304 round bar 1.500

Location	Loc Qty	Loc Code
MAT029	15.33	
106260	3.5	
114676	11.83	

. .

W/O:			WC	RK ORDER CHAN	GES							
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Da	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		·										
Part No	·	PAR #:	Fault Cated	gory:	NCR: Yes No DQA: Date:							
Resolution:			Disposition	າ:				Date: _				
NCR:			WORK ORDI	ER NON-CONFORM	JANCE (N	CR)	,					
DATE	STEP	Description of NC		ection B	V	/erification	Approval	Approval				
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section C	Chief Eng	QC Inspector			
							.•					

D3065-5DART AEROSPACE LTD	Work Order:	49053		
Description: Clevis	Part Number:	D3443-3		
Inspection Dwg: D3443 Rev: C		Page 1 of 1		

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article	Prototype	
---	---------------	-----------	--


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of inspection	Comments
2.70	+/-0.030	2.7/0			20,02	
0.95	+/-0.030	.955				
Ø0.500	+0.000/-0.005	. 498				
20°	+/-0.5°	200			2 profracto	
R0.450	+/-0.010	2.450			2,900	
Ø0.375	+0.006/-0.001	. 377			gage pin	
0.451	+/-0.010			_	,,,	, , , , , , , , , , , , , , , , , , ,
0.625	+/-0.010	,625			20.02	
1.43	+/-0.030	1.443				
_ .0.720 _	+/-0.010					
0.05 x 45°	+/-0.5°	,012 × 45	• //			
45°	+/-0.5°	45.				· sa :
1.00	+/-0.030	.999			(
1.125	+/-0.010	1.124				
0.438	+0.005/-0.000	2442			gage on	
R0.219	+/-0.010	2 219			gage pin	
					J	
						·

Measured by:	Audited by:	L.S	Prototype Approval:	N/A
Date: 11 . 5 . 17	Date:	11/18	Date:	N/A


Rev	Date	Change	Revised by Approve	ed
· A	06.06.28	New Issue	KJ/JLM10	
В	09.11.04	Dimensions updated per Dwg Rev C	KJ 9K) M	-

W/O:			V	VORK ORDER CHANGES					_
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
Part No:		PAR #;	_ Fault Ca	tegory: N	CR: Yes	No DQ	A:	Date:	
Resolution:			_ Disposit	ion: Q	A: N/C CI	osed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMANC	CE (NCF	R)			
DATE	STEP Description of NC		Initial	Sign 8	Sign & Verification Section C		Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng	Date			Chief Eng	QC Inspector
		,							


H:\fFQRMS\Quality Assurance\approved QA\NCRWO RevE



	_									
W/O:	 		WC	RK ORDER CHANG	ES			r		
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	lo DQA:	Date: _			
·					QA: N/C Closed: Date:					
NCR:		·	WORK ORDI	ER NON-CONFORMA	NCE (NCR)					
DATE	STEP	Description of NC		Corrective Action Section		Verification		Approval QC Inspector		
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng			
				-						
•										



W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	CEDURE CH	IANGE			Ву	Date	Qty	. Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				-5	8] 1	•				• • •		
		,							• .			
		gà.··			•					•		
		·								٠		
			•			٠		,				
	ام من بيونو ا	PAR #:	Fault Ca	tegory:			NCR: Yes	No DQ	A:	_ Date: _	,	
	R	esolution:	Disposit	ion:		· 	QA: N/C C	closed:		Date: _		
NCR:		V	ORK OR	DER NON	-CONF	ORMAN	CE (NC	R)				
DATE	STEP	Description of NC				Section 8			cation	Approval	Approval	
	SILF	Section A	Initial Chief Eng	Actio	on Descri Chief Eng	ption	Sign Date		ion C	Chief Eng	QC Inspector	
										•		
		·						, · ·		· 		
											· · ·	
		·										
Í	,											



DESIGN DART AEROSPACE LTD .
HAWKESBURY, ONTARIO, CANADA RF DRAWN RF CHECKED DRAWING NO. REV. C D3443 MFG. APPR. SHEET 3 OF 4 TITLE APPROVED SCALE STRUT WELDMENT ASSEMBLYNTS DE APPR. COPYRIGHT © 2005 BY DART AEROSPACE LTD


DATE

09.06.25

2

8

	•									
W/O:			WC	ORK ORDER CHANGI	ES				,	
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		······································								
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _		
	R	esolution:	Dispositio	n:	_ QA: N/C C	VC Closed: Date:				
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NC	₹)				
DATE	STEP	Description of NC Section A		on B		cation		Approval		
DAIL			Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector	
l										



W/O:			V	ORK ORDER CHAN	IGES					.6 /	
DATE	STEP	PRO	OCEDURE CH	IANGE	By Date Q				Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						'					
Part No:		PAR #:	Fault Ca	tegory:	NCI	R: Yes	No DQA	\:	Date: _		
Resolution:			Disposit	ion:	QA:	N/C Cld	C Closed: Date:				
NCR:			WORK OR	DER NON-CONFORI	MANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section B			Sign &	Verific		Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	n 	Date	Section	on C	Chief Eng	QC Inspector	
1											
										,	
										-	